

**Appendix G**  
**Quality Level Designation and Record**

Date: 04/20/2000

Quality Level: 3

**Note:** Assign and record quality level in accordance with MCP-540, and obtain appropriate approvals. Completed and approved form becomes a quality assurance record. (Master Equipment List may be used as a Q-List.)

04/20/2000  
Date

4/20/2000  
Date